

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION  
CERTIFICATE**

No. 26/20/1/2020

Date: 20/1/2020

It is certified that an inspection team headed by DR. Pradeep shir-  
Prasad Birtariya (Name of Officers  
with designation) from PHC Gumthala Teh Kampti (Name of  
Department/Office) inspected the K. John Public School  
Assoli Teh Kampti, Nagpur (Name & Address of  
the school) on 19/1/2020 and found that the K. John Public  
School Assoli T. Kampti NAGP (Name of school)  
has safe drinking water facilities for the students and member of staff of the institution and is  
maintaining the hygienic sanitation condition in the school building & the campus as per the  
norms prescribed by the central /State/UT Govt.

Signature with Seal : \_\_\_\_\_

Name

Designation

DR. Pradeep Birtariya  
मुख्य अधिकारी  
आरोग्य सेवा  
गुमथला, त. काम्पटी, ज. नागपुर  
: Mo I/C PHC  
Gumthala

To

The Principal  
K. John Public  
School, Assoli

PO, Assoli Dist. Nagpur  
Bhandara Road, NAGP.  
(Name & Address of the Institution)

**Manager**  
**K. John Public School**  
**Assoli, Bhandara Road,**  
**Nagpur.**

Principal  
**PRINCIPAL**  
**K. John public school (CBSE)**  
**Assoli, Bhandara Road,**  
**Nagpur - 441202**